

# Division of Waste Management Solid Waste Section

UNIT TYPE:												
Lined MSWLF		LCID	X	YW	Tra	insfer		Compost		SLAS		COUNTY: Alamance
Closed MSWLF		HHW		White goods	In	ncin		T&P		FIRM		PERMIT NO.: <b>N0673</b>
CDLF		Tire T&P / Collection		Tire Monofill		ustrial ndfill		DEMO		SDTF		FILE TYPE: COMPLIANCE

Date of Site Inspection: October 17, 2011 Date of Last Inspection: December 2, 2008

### **FACILITY NAME AND ADDRESS:**

Hinshaw's LCID Landfill 4337 S. NC Hwy 49 Burlington, NC 27215

**GPS COORDINATES**: N: 36.01753 E: 79.44917

#### **FACILITY CONTACT NAME AND PHONE NUMBER:**

Mike Hinshaw, Owner/Operator c. 336-260-7031 w. 336-570-1015 mikehinshaw@aol.com

#### **FACILITY CONTACT ADDRESS:**

Mike Hinshaw, Owner/Operator Hinshaw's LCID Landfill 4337 S. NC Hwy 49 Burlington, NC 27215

### **PARTICIPANTS**

John Patrone, NCDENR – Solid Waste Section (SWS) Mike Hinshaw, Owner/Operator

### **STATUS OF PERMIT:**

Land Clearing and Inert Debris Landfill Notification recorded with the Alamance County Register of Deeds September 9, 2005

Land Clearing and Inert Debris Landfill Notification approval letter dated October 3, 2005 issued by the SWS to Michael A. Hinshaw

Current status of the Land Clearing and Inert Debris Landfill Notification is OPEN

#### **PURPOSE OF SITE VISIT:**

Comprehensive Audit (to ensure that the notified land clearing and inert debris (LCID) landfill is in compliance with 15A North Carolina Administrative Code (NCAC) 13B .0563, .0564, and .0566)

### STATUS OF PAST NOTED VIOLATIONS:

None

### Division of Waste Management Solid Waste Section

Page 2 of 4

#### **OBSERVED VIOLATIONS**

None

The item(s) listed above were observed by Section staff and require action on behalf of the facility in order to come into or maintain compliance with the Statutes, Rules, and/or other regulatory requirements applicable to this facility. Be advised that pursuant to N.C.G.S. 130A-22, an administrative penalty of up to \$15,000 per day may be assessed for each violation of the Solid Waste Laws, Regulations, Conditions of a Permit, or Order under Article 9 of Chapter 130A of the N.C. General Statutes. Further, the facility and/or all responsible parties may be subject to enforcement actions including penalties, injunction from operation of a solid waste management facility or a solid waste collection service and any such further relief as may be necessary to achieve compliance with the North Carolina Solid Waste Management Act and Rules.

#### ADDITIONAL COMMENTS

On October 17, 2011, John Patrone met with Mike Hinshaw to conduct a comprehensive audit of Hinshaw's LCID Landfill on South NC Hwy 49 in Burlington, Alamance County.

- 1. Mr. Hinshaw owns Handgunners, Inc. (4325 S. NC Hwy 49, Burlington, NC 27215). Access to the land clearing and inert debris (LCID) landfill is via the parking lot serving Handgunners, Inc.
- 2. The LCID landfill footprint is estimated to be  $\sim 1.5$  acres.
- 3. The landfill area is designated, at each corner, by orange edge of waste markers.
- 4. The landfill side slopes are graded accordingly.
- 5. The landfill was adequately covered with soil. Mr. Hinshaw was grading the landfill area and covering material at the rear side slope during the inspection.
- 6. Adjacent to the landfill area are piles of soil and used asphalt. The asphalt will be spread atop the landfill and used as roadbed material, etc.

Phone: 336-771-5095 Fax: 336-771-4631

- 7. The facility occasionally stockpiles a few logs for firewood.
- 8. Prior to the landfill area, the facility stockpiles concrete to be used as roadbed material, etc.
- 9. Prior to the active area of the landfill, drivers are required to stop at a check-in area.
- 10. The LCID landfill appeared well operated and maintained.
- 11. No indication of erosion or runoff was observed.
- 12. Access roads are of all-weather construction.
- 13. The site is secured by locked steel cable.
- 14. The facility has proper signage.

Please contact me if you have any questions or concerns regarding this inspection report.

John Patrone

Environmental Senior Specialist

Regional Representative

Sent on: October 27, 2011	X	Email	Hand delivery	US Mail	Certified No. [_]

Copies: Dennis Shackelford, Eastern District Supervisor Shawn McKee, Environmental Senior Specialist

Division of Waste Management Solid Waste Section

Page 3 of 4

Digital photographs taken October 17, 2011 by John Patrone, DWM – SWS

Entrance sign to Handgunners, Inc., noting LCID landfill



Entrance sign to the LCID landfill (via the Handgunners, Inc. parking lot)



Stockpile of concrete, prior to landfill area



Driver check-in area, prior to active area of landfill



## Division of Waste Management Solid Waste Section

Page 4 of 4

View from front to back of LCID landfill



Rear view of LCID landfill, material in process of being covered with soil



View across LCID landfill



View from back to front of LCID landfill

